

DATE: December 3, 1973  
TO: Distribution  
FROM: M. S. Hodges  
SUBJECT: Multics Change Requests

Attached are copies of Multics Change Requests which were approved from November 16 through November 30, 1973

MULTICS CHANGE REQUEST

MCR 080  
Page 1 of 1 Pages

TITLE: Change to operator console software and syserr.

STATUS	DATE
Written	10/10/73
Approved <b>H</b>	<b>11/27/73</b>
Rejected	

AUTHOR: W. Silver

SOURCE: (if external) e.g., "User", "Marketing"

Postponed <b>H</b>	10/16/73
Withdrawn	
Expires	<b>5/27/74</b>

CLASSIFICATION	JUSTIFICATION	
	Incompatible Change	Marketing Requirement
X	Extension	Conformance to Standard
	Restriction	Increased Consistency
X	Performance Improvement	Simplification
X	Reliability Improvement	X Generalization
		X Bug Fix

Replaced by proposal MCR \_\_\_\_\_  
Implemented in System \_\_\_\_\_

Objections/Comments:  
MSB-108 should be updated and reissued as a MTB.

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

- REASONS:
1. Provide a logging mechanism for syserr messages.
  2. Provide buffering for operator console messages.
  3. Provide a better user interface to the operator console.

IMPLICATIONS:

Operations staff must be trained to use the new operator console interface.

MULTICS CHANGE REQUEST		MCR 151 Page 1 of 1 Pages
TITLE: Hardcore Updater Modifications		STATUS
AUTHOR: David M. Jordan		DATE
SOURCE: (if external) e.g., "User", "Marketing"		Written 11/5/73
		Approved <input checked="" type="checkbox"/> 11/27/73
		Rejected
		Postponed <input checked="" type="checkbox"/> 11/18/73
		Withdrawn
		Expires 5/27/74

CLASSIFICATION	JUSTIFICATION	
<input checked="" type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____ Implemented in System _____
<input type="checkbox"/> Extension	<input checked="" type="checkbox"/> Conformance to Standard	Objections/Comments: 1. Clarification of access to libraries 2. Information about user interface * * * * * 1. Access issue has been resolved 2. No important information is lost 3. "User" documentation should be submitted
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: 1: CACL's are being removed; 2: The MSL maintenance routines are becoming non-operable.

Summary: Modify the hardcore updater to 1) conform to new access control standards, 2) remove and partially replace the MSL, 3) convert to Version 2 PL/1, 4) generally cleanup.

Implications: 1) All hardcore (and salvager) library segments will have ACL's of r \*.\*., 2) some information previously kept in the MSL will be lost, but most will be obtainable through the Multics Installation System reporting procedures, 3) MSL maintenance procedures (bound\_msl\_ and bound\_lsm\_) may be deletable if no one else is using them.

Notes: A new procedure to maintain and retrieve information in a system id/update time corespondence data base will be written to replace most of the useful information contained in the MSL. The online system MIS reporting routines will be modified to make use of this information.

MULTICS CHANGE REQUEST

MCR 158  
Page 1 of 1 Pages

TITLE: Fix bug in print\_aste\_ptp when run on development

STATUS	DATE
Written	11/9/73
Approved <b>H</b>	11/20/73
Rejected	

AUTHOR: S. Webber

SOURCE: (if external) e.g., "User", "Marketing"

Postponed	
Withdrawn	
Expires	5/20/74

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
Extension	Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	X Bug Fix (Unreported)	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The tool print\_aste\_ptp has a constant wired into it which causes the command to fail if run on development.

SUMMARY: Change the constant to a variable which can be set from a value in the sst header.

IMPLICATIONS: None.

MULTICS CHANGE REQUEST		MCR <u>159</u> Page <u>1</u> of <u>1</u> Pages
TITLE: Fix bug in dump_segment_command  AUTHOR: <u>T. Casey</u>	STATUS	DATE
	Written	11/8/72
	Approved <b>H</b>	<b>11/20/73</b>
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	<b>5/20/74</b>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Implemented in System _____
<input type="checkbox"/> Extension	• Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Unreported Bug Fix	
<input type="checkbox"/>		

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Fix bug in implementation of short argument.

SUMMARY: Original implementation failed to print full address when it passed through a valve ending in 100 octal, if the line having that address was within a block of identical lines, printed as "====".

IMPLICATIONS: None.

MULTICS CHANGE REQUEST

MCR 160  
Page 1 of 1 Pages

TITLE: Emergency installation of gcos simulator

STATUS	DATE
Written	11/8/73
Approved <b>#</b>	<b>11/20/73</b>
Rejected	
Postponed	
Withdrawn	
Expires	<b>5/20/74</b>

AUTHOR: T. Casey

SOURCE: (if external) e.g., "User", "Marketing"

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
Extension	Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
X Reliability Improvement	Generalization	
	X Unreported Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: gcos simulator stopped working when 21.2 was installed because timer\_manager was recompiled for that system. The code generated by the current compiler is more sensitive to bad input argument values than the old one was.

SUMMARY: The cpu time passed to timer\_manager \$cpu call was essentially garbage. The old timer manager set a timer for verify far in the future, which caused no real problem. The bug was found and fixed by reading code, some weeks ago, but not installed then because it was causing no problem. Subsequently, the source and object archives were modified, while the experimental bound segment was not. When the latest system caused it to stop working (timer runouts occurred before the return from timer\_manager \$cpu call) the bound segment was installed but source and archives were not.

IMPLICATIONS: Library source is no longer current. Planned installation in about two weeks will fix that problem.

MULTICS CHANGE REQUEST		MCR <u>161</u>
TITLE: msa_manager_ bug fix	STATUS	DATE
AUTHOR: G. C. Dixon	Written	11/03/73
SOURCE: (if external: e.g., "User", "Marketing") local	Approved	11/20/73
CLASSIFICATION	JUSTIFICATION	Expires
Incompatible Change	Marketing Requirement	Replaced by proposal MCR
Extension	Conformance to Standard	Implemented in System
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Unreported Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASON:

When msa\_manager\_ attempts to load a non-initialized pointer value using an epp5 pr61140,\* instruction, an illegal procedure fault can occur if the contents of pr61140 contains an illegal modifier.

SUMMARY:

Assign a null pointer value to the above location.

IMPLICATIONS:

Random illegal procedure faults will no longer be caused by msa\_manager\_.

39919

MULTICS CHANGE REQUEST

MCR 162

TITLE: Fix bug in message coordinator.	STATUS	DATE
AUTHOR: T. H. Van Vleck	Written	11/01/73
SOURCE: (If external; e.g., "User", "Marketing")	Approved	11/20/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	5/20/74

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal 108
Extension	Conformance to Standard	Implemented in System
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Bug Fix #191	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

When a wakeup signal is lost, the message coordinator may end up with a stack of un-routed messages in mc.message. Currently, one wakeup is required to cause each message to be routed. Thus, subsequent system execution appears normal, except that the initializer console remains a constant number of messages "behind". Wakeups may be lost for a variety of reasons, such as ITT overflow.

SUMMARY:

Modify message\_coordr\_router to route up to 20 waiting messages to their virtual consoles on any wakeup. Extraneous wakeups are already ignored.

This will cause the coordinator to get back in synch after only a few successful wakeups.

IMPLICATIONS:

Eliminate a problem which has caused operational difficulties.



MULTICS CHANGE REQUEST

MCR 163

TITLE: Fix bug in ed_installation_parms.	STATUS	DATE
AUTHOR: VanVleck	Written	11/01/73
SOURCE: (if external: e.g., "User", "Marketing")	Approved	11/20/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	5/20/74

CLASSIFICATION	JUSTIFICATION	
		Replaced by proposal MCR
<input type="checkbox"/> Incompatible	<input type="checkbox"/> Marketing	
<input type="checkbox"/> Change	<input type="checkbox"/> Requirement	Implemented in System
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance	
<input type="checkbox"/> Restriction	<input type="checkbox"/> to Standard	Objections/Comments:
<input type="checkbox"/> Performance	<input type="checkbox"/> Increased	
<input type="checkbox"/> Improvement	<input type="checkbox"/> Consistency	
<input type="checkbox"/> Reliability	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Improvement	<input type="checkbox"/> Generalization	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Unreported	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

There is a bug in ed\_installation\_parms such that garbage is printed instead of a category name, due to an incorrect call to loa\_.

SUMMARY:

This is a one-line change to the call to loa\_.

IMPLICATIONS:

Fix bug.

MULTICS CHANGE REQUEST		MCR <u>164</u>
TITLE: Prevent Initializer from looping if a process cannot be destroyed.		STATUS: <u>Written</u>   DATE: <u>11/01/73</u>
AUTHOR: T. H. Van Vleck		<u>Approved</u>   <u>11/20/73</u>
SOURCE: (if external: e.g., "User", "Marketing")		<u>Rejected</u>
		<u>Postponed</u>
		<u>Withdrawn</u>
		<u>Expires</u>   <u>5/20/74</u>
CLASSIFICATION	JUSTIFICATION	
<u>Incompatible</u>	<u>Marketing</u>	<u>Replaced by proposal MCR</u>
<u>Change</u>	<u>Requirement</u>	<u>Implemented in System</u>
<u>Extension</u>	<u>Conformance</u>	
<u>Restriction</u>	<u>to Standard</u>	Objections/Comments:
<u>Performance</u>	<u>Increased</u>	
<u>Improvement</u>	<u>Consistency</u>	
<input checked="" type="checkbox"/> <u>Reliability</u>	<u>Improvement</u>	
<u>Improvement</u>	<u>Simplification</u>	
	<input checked="" type="checkbox"/> <u>Generalization</u>	
	<input checked="" type="checkbox"/> <u>Bug Fix #163</u>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

The initializer currently waits in ring 0 for a process to destroy itself. If the process cannot be destroyed, for instance because of a bug in ring 0 or damage to its PDS, the initializer will wait forever, and the system will have to be crashed.

SUMMARY:

The change described in MCR-023 added the ability for the initializer to block in ring 4 waiting for the process to die. This change adds a new "wait state" to the initializer for each process, which is entered when the process destruction is requested. When the "stopstop" wakeup is sent by traffic control, the initializer will complete the process destruction, and create a new process or type a logout message as necessary.

Fairly substantial modifications were necessary to dialup\_, caemon\_user\_manager\_ and absentee\_user\_manager\_.

In the process of making this change it was convenient to split the parsing of the login line into a separate program from the rest of dialup\_. This will come in handy if and when we allow user requests for new\_proc to be placed in a message segment and to specify arguments like those at login.

IMPLICATIONS:

Eliminate occasional crashes.

MULTICS CHANGE REQUEST		MCR <u>165</u>
TITLE: Remove installation-dependent ACL's from system tape.	STATUS	DATE
AUTHOR: VanVleck	<u>Written</u>	<u>11/02/73</u>
SOURCE: (If external; e.g., "User", "Marketing")	<u>Approved</u>	<u>11/30/74</u>
	<u>Rejected</u>	
	<u>Postponed</u>	
	<u>Withdrawn</u>	
	<u>Expires</u>	<u>5/30/74</u>
CLASSIFICATION	JUSTIFICATION	
		<u>Replaced by proposal MCR</u>
<input type="checkbox"/> Incompatible	<input type="checkbox"/> Marketing	
<input type="checkbox"/> Change	<input type="checkbox"/> Requirement	<u>Implemented in System</u>
<input type="checkbox"/> Extension	<input checked="" type="checkbox"/> Conformance	Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> to Standard	
<input type="checkbox"/> Performance	<input type="checkbox"/> Increased	
<input type="checkbox"/> Improvement	<input type="checkbox"/> Consistency	
<input checked="" type="checkbox"/> Reliability	<input checked="" type="checkbox"/> Simplification	
<input type="checkbox"/> Improvement	<input type="checkbox"/> Generalization	
	<input checked="" type="checkbox"/> Unreported	
	<input type="checkbox"/> Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

#### REASONS:

Supervisor gate segments are given their access control lists when the system is loaded from the system tape. Currently, the system tape contains many project names and user names in access control lists which represent local MIT policies concerning who may access specified gates. Most installations will not have, for example, a project named "PDO"; or if they do, their PDO project probably should not have access to phcs\_.

#### SUMMARY:

A new facility has been added to the supervisor recently which allows the initializer to set the ACL of a ring-zero segment. This facility will be used in the system\_start\_up.ec to set the correct gate ACL's. The system tape header will be modified to give access only to \*.SysDaemon.\* for those gates which are not available to all users. (Remember, the initializer's access name will be changed to "Initializer.SysDaemon.z" as described in MCR 041.)

#### IMPLICATIONS:

The privileged call to set gate ACL's is already being used in system\_start\_up.ec, so that the facility is known to work. The system\_start\_up.ec has always been a sensitive segment; this modification does not change the situation. It will no longer be necessary to generate a new system in order to give some user access to privileged gates or to clean up when a privileged user has finished his project. By making the maintenance of these privileged gates easier, installations will be encouraged to keep their system secure.

MULTICS CHANGE REQUEST

MCR 166

TITLE: Fix IO Daemon handling of multi-segment files.	STATUS	DATE
AUTHOR: VanVleck	Written	11/04/73
SOURCE: (If external: e.g., "User", "Marketing")	Approved	11/20/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	5/20/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible	Marketing	Replaced by proposal MCR
<input type="checkbox"/> Change	Requirement	Implemented in System
<input checked="" type="checkbox"/> Extension	Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	Unreported Bug Fix	
<input type="checkbox"/>		

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

When the IO Daemon prints a multi-segment file, it often happens that a line in the file is split across two segments. The printer DCM, when called to write the first part of such a line, has no way of telling that the next call will be a continuation of the line, so it appends a new-line character. This action means that an extraneous new-line character breaks every line which is split across segment boundaries, destroying the lineup of columns.

SUMMARY:

There is no reasonable way to explain to the printer DIM or DCM what action is desired here, since neither module has any concept of multi-segment file. Modifying the "file\_" DIM and the PL/I stream I/O mechanisms to prevent the splitting of a line across a segment boundary would not catch all cases of multi-segment file generation (e.g. PL/I listing files). The best place to fix this peculiar problem seems to be in the IO daemon program, which does know that it is processing a multi-segment file and can check for this case.

The modification involves providing a buffer, which will be filled with the two parts of the split line, and will be written

Fix IO Daemon handling of multi-segment files.

11/04/73

out by a special call in the IO daemon program.

Some reasonable maximum size for the buffer must be chosen -- say 512 characters. If the line which is split is longer than this, then the daemon will act as it does today.

IMPLICATIONS:

Better-looking output will be produced. A little bit of extra code will be executed for each multi-segment file break.

MULTICS CHANGE REQUEST

MCR 167

TITLE: Fix bug in ARDS charging.	STATUS	DATE
AUTHOR: VanVleck	Written	11/02/73
SOURCE: (If external: e.g., "User", "Marketing")	Approved	4/30/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	5/20/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible	Marketing	Replaced by proposal MCR
<input type="checkbox"/> Change	Requirement	Implemented in System
<input type="checkbox"/> Extension	Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
	<input checked="" type="checkbox"/> Unreported Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

Use of 1200-baud lines is currently charged incorrectly. A missing line of code in "device\_acct\_" causes attached devices to be charged connect timefrom the beginning of the session instead of from the last update, so that the charges go 1,2,3,4,5,... instead of 1,1,1,1,...

SUMMARY:

This is a one line fix to device\_acct\_.

IMPLICATIONS:

Charges will be correct.

MULTICS CHANGE REQUEST

MCR 168

TITLE: Modify disk accounting programs to use new quota primitives.

STATUS | DATE

AUTHOR: VanVleck

Written | 11/02/73

Approved | 11/20/73

Rejected

SOURCE: (If external: e.g., "User", "Marketing")

Postponed

Withdrawn

Expires | 5/26/74

CLASSIFICATION | JUSTIFICATION

Replaced by proposal MCR

Incompatible  
 Change

Marketing  
 Requirement

Implemented in System

Extension

Conformance  
 to Standard

Objections/Comments:

Restriction

Increased  
 Consistency

Performance

Simplification

Improvement

Reliability

Generalization

Improvement

Unreported

Bug Fix

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

When system 21.0 was installed, the time-page-product cell in the directory was expanded from fixed bin (35) to fixed bin (71), to avoid meter overflow in large directories. New quota-manipulation entries were added to hcs\_, which perform the same function as the old ones but have a fixed bin (71) argument for the time-page-product. The accounting system must be modified to use the new hcs\_ entries.

SUMMARY:

Two administrative tools are directly affected: these are sweep and reset\_disk\_meters. These two programs will call the new hcs\_ entries instead of the old ones.

The declaration of the segment "disk\_stat", which contains the disk usage meters, must be reformatted to hold the larger value. This change will require recompilation of the programs change\_disk and disk\_stat\_print.

The per-project disk usage totals in "projfile" and "use\_totals" is already fixed bin (71), so the rest of the accounting programs will not be affected.

Modify disk accounting programs to use new  
quota primitives.

11/02/73

Because this problem has now happened three times in the history of the system, and has required extraordinary efforts every time to repair the damage, the disk usage measurement programs will be modified to include an appropriate "gullibility test," which will check that the charge increment for a directory is not wildly inconsistent with the current occupancy and time since the last run of the program. If the program detects any problems, it can issue a warning message, which will alert us to the possibility of a supervisor bug immediately.

IMPLICATIONS:

The "disk\_stat" data base is completely re-created every night, so that no installation problems should ensue.



MULTICS CHANGE REQUEST

MCR 169

TITLE: Set TIMAX for Initializer to 1 second  
Instead of 0.

STATUS DATE

AUTHOR: VanVleck

Written 11/03/72

Approved 11/20/73

Rejected

SOURCE: (If external: e.g., "User", "Marketing")

Postponed

Withdrawn

Expires 5/20/74

CLASSIFICATION JUSTIFICATION

Replaced by proposal MCR

Incompatible Change

Marketing Requirement

Implemented in System

Extension

Conformance to Standard

Objections/Comments:

Restriction

Increased Consistency

Performance Improvement

Simplification

Reliability Improvement

Generalization

Bug Fix

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

During problems with the initializer (since fixed) we noticed that its extremely high scheduling priority made it impossible for any other process to get much done if the initializer was in a loop. Sometimes, system programmers could have patched the problem except that they could not get the CPU time necessary to make the patch. Furthermore, the standard procedure in this case is for the operator to enter BOS manually and use BLAST to tell all users that the system will go down in one minute, and then to issue a GO so that users may write out their editing; if the initializer is looping, users will not be able to finish their writes.

It was also noted that, under heavy load, the TIMAX of 0 for the initializer caused the scheduler to preempt any time the initializer was ready to run, and it was feared that this was degrading response on a one-CPU system under heavy load.

SUMMARY:

We performed an experiment to see what would happen if the initializer's TIMAX was set to 1. A "set\_timax 1" command was added to system\_start\_up.ec so that the initializer would have its TIMAX set to 1 every time the system came up. There were no

Set TIMAX for Initializer to 1 second  
instead of 0.

11/08/73

observed negative effects: logins didn't slow down noticeably,  
nor did system performance change observably.

We are currently running with a TIMAX of 1 on the initializer.

By changing one line in tc\_init, we can have 1 second be the  
default value. It looks like this won't do any harm and may help  
if the system has problems.

#### IMPLICATIONS:

When this change is installed, one line from system\_start\_up.ec  
can be removed, and one less message will be typed during system  
startup.

MULTICS CHANGE REQUEST

MCR 170  
Page 1 of 1 Pages

TITLE: Fix bug in truncate command when called with no arguments  
 AUTHOR: C. T. Clingen  
 SOURCE: (if external) e.g., "User", "Marketing"

STATUS	DATE
Written	11/12/73
Approved	11/20/73
Rejected	
Postponed	
Withdrawn	
Expires	5/20/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix #210	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: When truncate is called with no arguments, it reports the error and then prints out garbage.

SUMMARY: A variable is not properly initialized; the fix is to initialize it to a blank character string and in one case, make an assignment to it before it is used.

IMPLICATIONS: None. This fix has been made and checked out.

MULTICS CHANGE REQUEST		MCR <u>171</u> Page <u>1</u> of <u>1</u> Pages	
TITLE: <u>Fix bug in trace</u>	STATUS	DATE	
	Written	11/14/73	
	Approved	11/20/73	
AUTHOR: <u>M. J. Grady</u>	Rejected		
SOURCE: (if external) e.g., "User", "Marketing"	Postponed		
	Withdrawn		
	Expires	5/20/74	

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Implemented in System _____
<input type="checkbox"/> Extension	Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Unreported Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Fix a bug in trace which incorrectly computes the length of the line to be printed on PRT 300's.

SUMMARY: Change two lines of code on trace

IMPLICATIONS: None

MULTICS CHANGE REQUEST

MCR 172  
Page 1 of 1 Pages

TITLE: Implementation of the G115 remote computer interface	STATUS	DATE
	Written	11/14/73
	Approved	11/20/73
	Rejected	
AUTHOR: M. J. Grady	Postponed	
	Withdrawn	
	Expires	5/20/74
SOURCE: (if external) e.g., "User", "Marketing"		

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	<input checked="" type="checkbox"/> Marketing Requirement	Implemented in System _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The capability to run remote I/O devices must be added to Multics.

SUMMARY: Design and code a ring 4 DIM and DCM to implement the remote computer interface, and modify the TTY DIM to run high-speed synchronous devices.

IMPLICATIONS AND

DETAILED PROPOSAL: See MSB-110. Note that the MSB does not describe the ring 4 code as both a DIM and DCM. The DCM was created because the answering service requires asynchronous I/O which is not supported by the ios\_ interface. The DIM-DCM interface is similar to tw\_ - tty DIM interface.

MULTICS CHANGE REQUEST		MCR <u>173</u>
TITLE: Install new version of trace_stack.	STATUS	DATE
AUTHOR: T. H. Van Vleck	Written	11/15/73
	Approved	11/27/73
	Rejected	
SOURCE: (If external: e.g., "User", "Marketing")	Postponed	
	Withdrawn	
	Expires	5/27/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible	<input type="checkbox"/> Marketing	Replaced by proposal MCR
<input type="checkbox"/> Change	<input type="checkbox"/> Requirement	Implemented in System
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Conformance	Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> to Standard	
<input type="checkbox"/> Performance	<input checked="" type="checkbox"/> Increased	
<input type="checkbox"/> Improvement	<input type="checkbox"/> Consistency	
<input checked="" type="checkbox"/> Reliability	<input checked="" type="checkbox"/> Simplification	
<input type="checkbox"/> Improvement	<input type="checkbox"/> Generalization	
	<input checked="" type="checkbox"/> Unreported	
	<input type="checkbox"/> Bug Fix	
	<input checked="" type="checkbox"/> Bug Fix	
	#138 (half)	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

This version of trace\_stack uses the new fault information primitives created by Melanie Weaver and described in MCR-055.

The trace\_stack command will perform more reliably in several cases, and will be less vulnerable to system changes, since the new fault information primitives embody much of the implementation-dependent code.

SUMMARY:

All modules of bound\_trace\_stack\_ change.

IMPLICATIONS:

Minor changes have been made to the output format. If a pointer argument points to a character string longer than 4 characters, the contents of the string will be printed in parentheses.

A new program called "extract\_source\_line\_" has been added, which is called by print\_source\_line\_ and which could be called by debug when it wishes to obtain a source line.

MULTICS CHANGE REQUEST

MCR 174  
Page 1 of 1 Pages

TITLE: Fix locking bug in find\_

STATUS	DATE
Written	11/16/73
Approved #	11/27/73
Rejected	

AUTHOR: A. Kobziar

SOURCE: (if external) e.g., "User", "Marketing"

Postponed	
Withdrawn	
Expires	5/27/74

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	<input type="checkbox"/> Implemented in System _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix #207	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: If find\_ \$ dir is called with a pathname of ">>...." it will leave the root locked. Depending on the load on the system this can deteriorate performance or even crash the system.

SUMMARY: Change find\_ to return "argerr" for erroneous pathnames.

MULTICS CHANGE REQUEST

MCR 175  
Page 1 of 1 Pages

TITLE: BOS should not set masks in memory controllers from which it is not receiving interrupts.

STATUS	DATE
Written	11/16/77
Approved <i>H</i>	<i>11/27/73</i>
Rejected	

AUTHOR: R. Mullen

SOURCE: (if external) e.g., "User", "Marketing"

Postponed	
Withdrawn	
Expires	<i>5/27/74</i>

CLASSIFICATION

JUSTIFICATION

Replaced by proposal MCR \_\_\_\_\_

Incompatible Change

Marketing Requirement

Implemented in System \_\_\_\_\_

Extension

Conformance to Standard

Objections/Comments:

Restriction

Increased Consistency

Performance Improvement

Simplification

Reliability Improvement

Generalization

Unreported

Bug Fix

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: BOS will hang if it attempts to read or set masks in memory controllers for which the running cpu is not the control processor.

SUMMARY: The memory on each cpu port can be tested with the rscr instruction to determine if the running cpu is the control processor.

IMPLICATIONS: None

DETAILED PROPOSAL: This check can be placed naturally in get port info where it will be executed whenever bos is entered or exited, before masks are read or set.



MULTICS CHANGE REQUEST

MCR 177  
Page 1 of 1 Pages

TITLE: Type message on printer error in BOS

STATUS	DATE
Written	11/19/73
Approved <b>H</b>	<b>11/27/73</b>
Rejected	

AUTHOR: N. I. Morris

SOURCE: (if external) e.g., "User", "Marketing"

Postponed	
Withdrawn	
Expires	<b>5/27/74</b>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	<input type="checkbox"/> Implemented in System _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	
<input checked="" type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix #156	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The printer can halt during BOS dumps with no indication of the malfunction on the operator's console.

SUMMARY: Print message when bad status is received from the printer.

MULTICS CHANGE REQUEST

MCR 178  
Page 1 of 1 Pages

TITLE: Fix "all 5's" bug in full_ipc_	STATUS	DATE
	Written	11/21/7
AUTHOR: Robert Mullen	Approved #	11/27/73
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	5/27/74

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
Extension	Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	X Bug Fix #140	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Presently full\_ipc\_ does not verify that an event\_channel\_name is legal before copying itt messages, if the message is a device signal. The ensuing error creates an unnecessary answering service dump.

SUMMARY: This can be prevented by verifying the event\_channel\_name in all cases.

IMPLICATIONS: This fix has been tested on development machine and does not seem to have any further implications.

MULTICS CHANGE REQUEST		MCR <u>179</u> Page <u>1</u> of <u>1</u> Pages
TITLE: <u>gcos_daemon bug fixes</u>	STATUS	DATE
AUTHOR: <u>P. Haber</u>	Written	<u>11/22/73</u>
	Approved <u>H</u>	<u>11/27/73</u>
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	<u>5/27/74</u>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
Incompatible Change	Marketing Requirement	Implemented in System _____
Extension	• Conformance to Standard	Objections/Comments:
Restriction	Increased Consistency	
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	X Unreported Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:

- 1) Include file lost during installation retyped.
- 2) Default condition handler was established in a subroutine which returned.
- 3) References to unimplemented "gcos" bit in absentee include file detected.

SUMMARY:

- a) Move default condition handler to main procedure.
- b) Retype in missing include file.
- c) Delete references to "gcos" bit in absentee include file.

IMPLICATIONS:

- a) Will allow daemon to take faults w/o terminating.
- b) Replacement of missing source
- c) Avoids setting extraneous bit

Note: Change a) in summary already implemented in Phoenix.