

DATE: December 19, 1973
TO: Distribution
FROM: M. S. Hodges
SUBJECT: Multics Change Requests

Attached are copies of Multics Change Requests which were approved from December 1 through December 15, 1973.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.

MULTICS CHANGE REQUEST

MCR 176
Page 1 of 2 Pages

TITLE: Install "iox_" I/O interface (MSB-113).

STATUS	DATE
Written	11/16/73
Approved H	12/4/73
Rejected	
Postponed	11/27/73
Withdrawn	
Expires	6/4/74

AUTHOR: M. G. Smith

SOURCE: (if external) e.g., "User", "Marketing"

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	<input checked="" type="checkbox"/> Marketing Requirement	Implemented in System _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Objections/Comments: Postponed for further details. ***** Approved subject to the usual performance and documentation requirements. A plan for subsequent related installations is being published. An additional MTB is being published.
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	
<input checked="" type="checkbox"/> Performance Improvement	<input checked="" type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: There is a marketing requirement that Multics provide to its customers (1) very efficient implementation of conventional (i.e., PL/I, FORTRAN, and COBOL) I/O access methods to (2) record files, both indexed and unindexed, which reside interchangeably (3) in the Multics file system or on demountable user tape and disk volumes.

In addition, there is an internal requirement (for the efficient design and implementation of language I/O) for a rigidly-specified common I/O interface to be used by all language processors.

The existing I/O switch interface and mechanism are deficient for these purposes in that they (1) involve unnecessary overhead (a table look-up and an extra complete push/call sequence); (2) do not accommodate the necessary operations for indexed files; (3) are so loosely-specified as to be unusable (e.g., any DIM can choose not to support any entry; any DIM can choose to redefine the meaning of any entry; any DIM can choose not to support any element sizes, breaks, delimiters, pointers); (4) do not decouple the operations of attachment and opening (necessary if programs are to be device-independent); and (5) require, for the construction of IOSIMS, that the customer use assembly language, which we wish strongly to discourage.

SUMMARY: (1) Install a new I/O system interface, known as "iox_", as described in MSB-113 and MTB-010, alongside the existing "ios_" system.
 (2) Replace the existing "ios_" implementation with one which, as appropriate, (a) maps old calls into new ones (so that existing unconverted programs can use converted DIMs); (b) maps new calls into old ones (so that converted programs can use existing unconverted DIMs); and (c) passes old calls straight through (so that existing unconverted programs can continue to use existing unconverted DIMs).
 (3) Convert the most common system procedures (command loop, "ioa_", "file_output") to call the new I/O system interface.
 (4) Provide a new file DIM which implements very efficient access to stream and unindexed record files stored in the Multics hierarchy (the other new DIMs mentioned in MSB-113 are not a part of this MCR, and are to be separately proposed).

IMPLICATIONS: (1) All existing software, both system and user, will continue to work unchanged. The provision of the new I/O interface alongside the old will in no way interfere with the functioning of programs or DIMs making use of the old interface.

(2) On an as-needed or as-convenient basis, any existing programs or DIMs can be converted to use the new interface directly, when they desire to secure the additional efficiency or functionality.

(3) The installation of the new I/O interface is a prerequisite to the availability of record I/O in our PL/I and FORTRAN implementations.

(4) While ultimately the new I/O interface is designed for a level of performance exceeding that attainable with the current interface, in the interim period (before existing programs and existing DIMs are converted over to use the new interface), existing programs may notice a performance degradation of 1.5 milliseconds/call due to the write-arounds involved. See the timing discussion included as an appendix to this MCR.

DETAILED PROPOSAL: Replace "ios_" (as described above), "real_init_admin_" and "process_overseer_" (to bring up processes with the new I/O system), "get_at_entry_" and "print_attach_table" (to extract the old information from new sources). Add "iox_", composed principally of the modules "attach" (new attach command), "attach_syn", "attach_tty" (which includes "attach_net", "attach_abs", "attach_mrd", "attach_oc", "attach_tek", and "attach_ec", and which implement the new I/O interface by calling the existing DIMs), "find_iocb", "io_call", "ios_call" (an ALM utility to allow PL/I calls to the transfer vectors of unconverted DIMs), "piocb" (a utility for printing the contents of I/O control blocks), "propagate", "attach_file" (the new file DIM), and "tw" (a write-around package which maps old I/O calls into new ones for typewriter-like DIMs). Change "file_output", "get_to_cl_", "lsn_util_" "real_sdh_", and "rest_of_ioa_" to call the new I/O interface.

APPENDIX: Some tests were made to ensure that system performance will not be adversely affected by this installation.

(1) Null command test. The c.p.u. time to go once around the command loop (execution of a "nothing" command) was metered. Existing command loop and "ios_" took $20.8+1.8$ milliseconds per trip around the loop. The new command loop (MCR-037) but still the old "ios_" took $22.3+1.1$ msec on the same test. The new command loop (but not modified to call "iox_": i.e., using the old-to-new write-arounds) and the new "iox_" took $23.9+2.4$ msec on the same test, an increase of 1.6 msec/trip, which is less than the standard deviation of the observed times. Note: It is not convenient to meter the old command loop with the new I/O system because "ios_" is bound with the old command loop.

(2) Null DIM test. The time to go once around an "ios \$write" call loop (execution of "ioa \$ioa_stream" through the "discard_output_" DIM) was metered. Existing "ios_" took 4.3 msec/trip. Replacement "ios_" took 5.7 msec/trip, an increase of 1.4 msec/trip. Inasmuch as neither the DIM nor the program had any significant processing to perform, this test represents the worst-case performance degradation to existing software due to installation of the replacement "ios_", namely a 33% increase in c.p.u. time.

(3) New file DIM test. The time to "ioa_" several thousand lines to a file via "file_output" was metered. The existing system took 10.4 msec/line. The new I/O system (including the new file DIM, but with an unconverted "ioa_" as caller) took 10.2 msec/line, a decrease of 2% in c.p.u. time expended.

(4) "ioa_" test. The existing system took 24.1 msec/line to "ioa_" several thousand lines to the console. The new I/O system (but using an unconverted "ioa_" and a teletype DIM write-around which called the old DIM) took 25.0 msec/line, an increase of 4% in c.p.u. time expended.

(5) "print" test. The existing system took 22.3 msec/line to print a large file with long lines onto the console. The new (but again unconverted "print" command and write-around DIM) took 23.5 msec/line, an increase of 5% in c.p.u. time.

In conclusion, the tests do not indicate any problematic decrease in performance during the interim period.

MULTICS CHANGE REQUEST		MCR 180 Page 1 of 1 Pages
TITLE: Correction to ARPA Network Self-identification Processing AUTHOR: D. Wells	STATUS	DATE
	Written	11/26/73
	Approved <i>H</i>	<i>12/4/73</i>
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	<i>6/4/74</i>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
Incompatible Change	Marketing Requirement	Implemented in System _____
Extension	Conformance to Standard	Objections/Comments:
Restriction	Increased Consistency	
Performance Improvement	Simplification	
Reliability Improvement	X Generalization	
	X Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:
MCR 174 included some changes to the ARPA Network Software to allow the MCP (Network Control Program) to determine the identifying number of the host where it was running by a named reference to the IMP DRI's data base. At that time, all known host number dependencies were altered to utilize this mechanism. Now that test facilities have become available, an additional dependency has been found.

SUMMARY: This MCR proposes the correction of this newly found host number dependency. The mechanism has now been tested and the MIT multics machine has now been operational on the Network as both host 6 and as host 44.

IMPLICATIONS:
MOSI 00.3 Revision 6 has been issued describing the use of the CONFIG card for the ARPA Network.

The MIT multics is currently scheduled (as announced to the Network Community by RFC 500) to switch from being host 6 (on the MIT-MAC IMP) to being host 44 (decimal) (on the MIT-IPC IMP) on Monday, December 17, 1973. This bug fix should be installed before that time; arrangements have already been made with MIT-IPC to facilitate this installation.

MULTICS CHANGE REQUEST		MCR <u>181</u> Page <u>1</u> of <u>1</u> Pages
TITLE: <u>Fix to DN 355</u>	STATUS	DATE
	Written	11/21
AUTHOR: <u>R. B. Snyder</u>	Approved <i>H</i>	12/4/73
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	6/4/74

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Implemented in System _____
<input type="checkbox"/> Extension	• Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	Increased Consistency	
<input checked="" type="checkbox"/> Performance Improvement	Simplification	
<input type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix #213	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Fix being made to prevent 355 crashes

SUMMARY: A bug exists wherein dn355 can pick up status words from the Datanet 355 out of order. The fix is to supply sequence numbers with the status words. (This fix had already gone in on an emergency basis.)

IMPLICATIONS: Fewer crashes.

MULTICS CHANGE REQUEST

TITLE: Fix to system_trace

AUTHOR: R. B. Snyder

SOURCE: (if external) e.g., "User", "Marketing"

STATUS	DATE
Written	11/21/73
Approved 12	12/4/73
Rejected	
Postponed	
Withdrawn	
Expires	6/4/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> (Unreported) Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: System trace needs a lock since two cpu's can attempt to write in trace at the same time.

SUMMARY: A lock will be used to prevent two cpu's from writing in system trace segment at the same time.

IMPLICATIONS: None.

MULTICS CHANGE REQUEST		MCR <u>183</u> Page <u>1</u> of <u>1</u> Pages
TITLE: Rewrite edm for speed and clarity	STATUS	DATE
AUTHOR: <u>Robert Mullen</u>	Written	11/27
SOURCE: (if external) e.g., "User", "Marketing"	Approved <i>H</i>	12/4/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	6/4/74

CLASSIFICATION	JUSTIFICATION	REASON
Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
Extension	Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: edm with eis is slower than the more complicated qedx in some cases.

SUMMARY: Use of structures for some variables will generate copying of them with MLR's.
 Use of label variables can be replaced by internal procedures. Some character operations are currently performed one at a time in loops.
 Several pieces of common code can be placed in internal procs. The strategy for certain requests has become wastefully memory intensive now that string operations have become relatively cheaper. Further improvements will become apparent as code is cleaned up.

IMPLICATIONS: No user interface to be changed.

DETAILED PROPOSAL: as above.

MULTICS CHANGE REQUEST

TITLE: New GCOS Simulator
AUTHOR: T. Casey

STATUS	DATE
Written	11/27/73
Approved #	12/4/73
Rejected	
Postponed	
Withdrawn	
Expires	6/4/74

SOURCE: (if external) e.g., "User", "Marketing"

CLASSIFICATION	JUSTIFICATION	
	Marketing Requirement	Replaced by proposal MCR _____
<input checked="" type="checkbox"/> Incompatible Change	X	Implemented in System _____
X Extension	Conformance to Standard	Objections/Comments: Modify 355 software installation tools as required.
Restriction	Increased Consistency	
Performance Improvement	Simplification	
Reliability Improvement	X Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Install experimental version of GCOS simulator.

SUMMARY: Implemented 32 more control cards than currently installed simulator supports, along with new software to support 7 new activity cards. Converted for 256K segments, max length, and eliminated append permission. Fixed many bugs. Changed error handling to be more like the real GCOS. Added \$ SELECTD card, and prepared for a future change to the \$ SELECT card.

IMPLICATIONS: The \$ SELECT card is used by the 355 software installation tools, in a context that would be incorrect in the real GCOS. They will have to be changed to use the \$ SELECTD card instead. The two cards will be processed identically in the version to be installed. In the next version, the \$ SELECT card will not work in this incorrect context. The installation tools should therefore be changed soon after this installation.

MULTICS CHANGE REQUEST		MCR <u>185</u> Page <u>1</u> of <u>1</u> Pages
TITLE: <u>Fix to BOS BLAST command</u>	STATUS	DATE
AUTHOR: <u>R. B. Snyder</u>	Written	<u>11/28</u>
	Approved H	<u>12/4/73</u>
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	<u>6/4/74</u>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Implemented in System _____
<input type="checkbox"/> Extension	Conformance to Standard	Objections/Comments: .
<input type="checkbox"/> Restriction	Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix (Unreported)	
<input type="checkbox"/>		

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The BOS BLAST command needs to wait until the 355 has completed sending the BLAST message to prevent that message from being clobbered by subsequent BOS commands.

SUMMARY: The BLAST command will loop for the time required to send the BLAST message out to a 110 baud terminal (the slowest).

IMPLICATIONS: None.

MULTICS CHANGE REQUEST

MCR 186
Page 1 of 1 Pages

TITLE: Place check in stop_process to crash system if called by initializer

STATUS	DATE
Written	11/28/73
Approved H	12/4/73
Rejected	
Postponed	
Withdrawn	
Expires	6/4/74

AUTHOR: S. Webber

SOURCE: (if external) e.g., "User", "Marketing"

CLASSIFICATION	JUSTIFICATION	
		Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	<input type="checkbox"/> Implemented in System _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	<input type="checkbox"/> Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Search for bug	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: It is possible for a user ring program to call hcs_\$ stop_process to have its process stopped. However, if this program gets invoked by the initializer things get very confusing and it is hard or impossible to find out why the initializer wanted to stop itself. Since the system will crash anyway if the initializer gets stopped I propose we crash it early so we find out why.

SUMMARY: Make simple check in stop_process.

IMPLICATIONS: None.

MULTICS CHANGE REQUEST

MCR 187

TITLE: make the date_time active functions
operate as commands

STATUS DATE

AUTHOR: Gary C. Dixon

Written 11/26/73

Approved 12/4/73

Rejected

SOURCE: (if external: e.g., "User", "Marketing")
local

Postponed

Withdrawn

Expires 6/4/74

CLASSIFICATION JUSTIFICATION

Replaced by proposal MCR

Incompatible Marketing

Change Requirement Implemented in System

Conformance

Extension to Standard Objections/Comments:

Increased

Restriction Consistency

Performance

Improvement Simplification

Reliability

Improvement Generalization

Bug Fix

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally
DETAILED PROPOSAL

REASONS:

Make the following active functions perform as commands:
date, date_time, day, day_name, hour, long_date, minute, month,
month_name, time, year.

SUMMARY:

If cu_saf_return_arg returns error_table_not_act_fnc, then
output the date/time string on the user_output stream instead of
returning it as the active function value.

IMPLICATIONS:

The date/time active functions will operate as commands,
eliminating the need for commands to perform the equivalent
function.

MULTICS CHANGE REQUEST

MCR 189

TITLE: Online Installation documentation	STATUS	DATE
AUTHOR: P. Kelley	Written	11/19/73
SOURCE: (If external; e.g., "User", "Marketing") local	Approved <i>H</i>	12/4/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	6/4/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible	Marketing	Replaced by proposal MCR
<input type="checkbox"/> Change	Requirement	Implemented in System
<input checked="" type="checkbox"/> Extension	Conformance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	Increased Consistency	
<input type="checkbox"/> Performance Improvement	Simplification	
<input type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

Reasons:

There are four areas of the online documentation program which require changing. They are: 1) add capability to produce formatted documentation for info files and include files; 2) reformat output to include time of installation along with a brief prose section specifying MCR number(s) and reason(s) for change; 3) add capability to update news.info at the time of installation; 4) specify an absolute pathname for the documentation log segment.

Summary:

Modifications will be made to the update_seg command to accept the optional argument "-log" when initiating an installation. The presence of this argument will ask for line input to be entered describing the installation. This variable length information will be passed to upd_doc_task_ at the time when documentation takes place during an installation.

Create the entry upd_doc_task_\$write_prose to accept this line input string, call a subroutine to format it, append it to the documentation log segment, and insert it in news.info.

Modify upd_doc_task_ to produce formatted output for info and include files, and to include the time of installation. Also, the pathname >ldd>online_installations>utility will be explicitly specified as the residence of the documentation log segment (instead of the current "working_dir").

Alter the relationship between upd_log_task_ and upd_doc_task_ so that upd_log_task_ is called by entries in upd_doc_task_ to create (if necessary) and lock the documentation log segment and news.info while appending information.

Implications:

This implementation will provide more accurate documentation (needed for publishing), improved readability, a permanent residence for documentation log, and an immediate update of news.info when an installation has taken place.

TASK DESCRIPTION	PERSONNEL	START	FINISH	M-W	CHANGES-STATUS
update_seg: add -log option and code to accept typed line input describing installation	Kelley			1	
upd_doc_task: produce formatted documentation for info & include files	Kelley			2	
upd_doc_task: add entry \$write_prose to format/add prose to the documentation log & news.info	Kelley			1	
upd_log_task: revise interface with upd_doc_task_	Kelley			4	
upd_install_task: add code to call upd_doc_task_\$write_prose	Kelley			2	

TITLE: Installation of TTYM	STATUS	DATE
	Written	11/28/73
AUTHOR: R. B. Snyder	Approved	# 12/4/73
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	6/4/74

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
Incompatible Change	Marketing Requirement	Implemented in System _____
Extension	• Conformance to Standard	Objections/Comments:
Restriction	Increased Consistency	
X Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Bug Fix	
	X Need to meter ttydim	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The uninstalled ttydim metering command TTYM will be converted to run on the 6180 and installed.

SUMMARY: TTYM needs a small bit of converting and in addition, a new subroutine entry `meter_gate` will be added to the command `meter_gate` to allow routines (TTYM in this case) to get gate metering data for an array of entry names. In addition, the include file `tty.incl.pll` will be modified to change the declarations of `tty_buf` and `tty_ctl` from `ext static` to `based` so that TTYM can use the include file to get out the meters.

IMPLICATIONS: The other users of the include file (`tty_inter`, `tty_write`, etc) will have to be changed to initialize a ptr to use the based overlays.

MULTICS CHANGE REQUEST		MCR <u>192</u>
TITLE: Fix bug in operator SUBSTTY command.	STATUS	DATE
AUTHOR: Dennis Capps	Written	11/29/73
	Approved	12/11/73
	Rejected	
SOURCE: (If external; e.g., "User", "Marketing")	Postponed	
	Withdrawn	
	Expires	6/11/74
CLASSIFICATION	JUSTIFICATION	
Incompatible	Marketing	Replaced by proposal MCR
Change	Requirement	Implemented in System
Extension	Conformance	Objections/Comments:
Restriction	to Standard	
Performance	Increased	
Improvement	Consistency	
Reliability	Simplification	
Improvement	Generalization	
	Bug Fix #215	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS:

System bug 215 is a bug in the message coordinator which causes the message coordinator to malfunction when an attempt is made to substitute one terminal for another. The substitution appears to work, and output messages come out on the new terminal for a while; then they stop, and further output lines from the system service processes "pile up" in the device queue. Manual intervention is necessary to get output started again.

SUMMARY:

The code which copies pending untyped output lines from the old terminal's queue to the new terminal's queue had an incorrect assumption about the value of a DO index when the loop exits. This caused mis-threading of the terminal queue which did not lose messages, but which caused the system to think that it did not need to send a device driver wakeup in some cases where this wakeup was actually needed.

IMPLICATIONS:

none

TITLE: <u>Modifications to network_exec_</u> AUTHOR: <u>Kenneth T. Pogran</u>	STATUS	DATE
	Written	11/30/73
	Approved #	12/11/73
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	Objections/Comments:
<input checked="" type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:

network_exec_ is being changed to:

1. Aid in tracking down severe Network hardware and software problems
2. Enforce a minimum time interval between re-initialization attempts during hardware problems, to avoid tying up the BOS console (and hence the system) with IMP DIM status messages.
3. Provide a functioning default handler for the Network Daemon process.
4. Add a call to ios_\$resetread upon entry to "exec" mode in the Network Daemon process.

MULTICS CHANGE REQUEST		MCR 195 Page 1 of 1 Pages
TITLE: Allow EAQ output in floating point	STATUS	DATE
AUTHOR: B. Wolman	Written	12/3/73
SOURCE: (if external) e.g., "User", "Marketing"	Approved	# 12/11/73
	Rejected	
	Postponed	
	Withdrawn	
	Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments: MPM writeup must be updated immediately to reflect this change.
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	
<input checked="" type="checkbox"/>	<input type="checkbox"/> Convenience	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Debugging programs which do floating-point calculations is complicated by the fact that EAQ register cannot be printed by debug command in floating-point format.

SUMMARY: Add "\$eaq" name to list of registers recognized by debug. The \$eaq request will display contents of floating accumulator in E format.

IMPLICATIONS: eaq will no longer be usable as a user register name.

STATUS: This fix is currently being used by me. It is ready to be installed.

MULTICS CHANGE REQUEST

TITLE: Put time out mechanism on waiting processes	STATUS	DATE
	Written	11/29/73
	Approved H	12/11/73
	Rejected	
AUTHOR: S. Webber	Postponed	
	Withdrawn	
	Expires	6/11/74
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
Incompatible Change	Marketing Requirement	Implemented in System _____
Extension	Conformance to Standard	Objections/Comments: 1. Assume no measurable degradation of system performance. 2. Another MCR expected to trace and locate actual problem.
Restriction	Increased Consistency	
Performance Improvement	Simplification	
X Reliability Improvement	Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Change pxss to "time out" on events being waited for. If a process "waits" (state 3) for more than say 30 seconds, pxss should give him a notify (zero the wait event, set the state to "ready") and print a message on-line. This will allow the system to automatically recover from "lost notifies".

SUMMARY: Minor changes to pxss to see if current time differs too much from "time state last changed" when a process is waiting.

IMPLICATIONS: None.

MULTICS CHANGE REQUEST		MCR <u>197</u> Page <u>1</u> of <u>1</u> Pages
TITLE: QEDX default path	STATUS	DATE
AUTHOR: <u>M. Meer</u>	Written	<u>12/4</u>
SOURCE: (if external) e.g., "User", "Marketing"	Approved <u>H</u>	<u>12/11/73</u>
	Rejected	
	Postponed	
	Withdrawn	
	Expires	<u>6/11/74</u>

CLASSIFICATION	JUSTIFICATION	
X Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
X Extension	Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Objections to current implementation of default pathname.

SUMMARY: Change output default pathname handling to make it easier to use.

IMPLICATIONS: Incompatible with current and past usage. May affect exec coms.

- DETAILED PROPOSAL:
- 1) There will be one default pathname per buffer.
 - 2) It will be set when a) reading into an empty buffer
b) writing using a pathname
 - 3) It will be set to null when reading into a non-empty buffer even if the same read pathname is used.
 - 4) It will initially be set to null.

I would appreciate advice on 3). Some people strongly object to ever losing the default. Possibly asking a question about resetting the default name and letting the user determine what is to be done.

The status command, x, will print the default together with the other information it already gives.

MULTICS CHANGE REQUEST

TITLE: Improvements to debug command

STATUS	DATE
Written	12/4/73
Approved #	12/11/73
Rejected	

AUTHOR: Robert S. Coren

SOURCE: (if external) e.g., "User", "Marketing"

Postponed	
Withdrawn	
Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	
		Replaced by proposal MCR _____
X Incompatible Change	Marketing Requirement	Implemented in System _____
X Extension	Conformance to Standard	Objections/Comments:
	X Increased Consistency	
	Performance Improvement	
	Reliability Improvement	
	X Unreported Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Improve accuracy of information provided by debug, make it consistent with trace_stack, new listener (MCR-037).

- SUMMARY:
1. Use bound_debug_utils_ (MCR-055).
 2. Start stack trace with actual first frame (instead of second as at present)
 3. Increase reliability of segment/entry names as used by debug.
 4. Correct improper reporting of sblaq, ssq, dfdi opcodes.
 5. Make stack depth numbers decimal rather than octal.

IMPLICATIONS: Item 2) above will cause normal stack frame indices to increase by 1.

A version that incorporates item 1) and 3) above has been >udd>m>lib>e since July.

This change depends on the installation of bound_debug_utils_ (MCR-055).

MULTICS CHANGE REQUEST		MCR 199 Page 1 of 1 Pages
TITLE: Remove obsolete tape software	STATUS	DATE
	Written	12/11/73
AUTHOR: N. Morris	Approved <i>H</i>	12/11/73
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing" Internal	Postponed	
	Withdrawn	
	Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	Increased Consistency	Objections/Comments:
<input checked="" type="checkbox"/> Performance Improvement	Simplification	
<input type="checkbox"/> Reliability Improvement	Generalization	
<input checked="" type="checkbox"/> Housecleaning	Bug Fix	
<input type="checkbox"/>		

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: tds_m is an obsolete version of tape_u, the Multics Standard Tape DSM. was replaced more than a year ago and was left in the system for compatibility. With the installation of tape reel management and MTS-500 software, tds_m will become unusable.

IMPLICATIONS: Any obsolete programs (there should be none) invoking tds_m will cease to work. (They probably don't work anyway since parts of tds_m were last compiled in March, 1972 in VIPL1.)

MULTICS CHANGE REQUEST		MCR <u>200</u> Page <u>1</u> of <u>1</u> Pages	
TITLE: Avoid hardware bug in slt_manager		STATUS	DATE
		Written	12/04/73
AUTHOR: <u>David M. Jordan</u>		Approved H	12/11/73
		Rejected	
SOURCE: (if external) e.g., "User", "Marketing"		Postponed	
		Withdrawn	
		Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	Conformance to Standard	Implemented in System <u>21.5a</u>
<input type="checkbox"/> Restriction	Increased Consistency	Objections/Comments: Retain system tape which fails as a "test case" and push to repair hardware.
<input checked="" type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
<input type="checkbox"/>	Bug Fix	
<input checked="" type="checkbox"/>	Hardware bug avoidance	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: CPU B does not properly handle page faults during the execution of RPD instructions.

SUMMARY: Modify slt_manager to remove a RPD loop in the comparison of segment names. Replace the RPD loop with a CMPC instruction.

IMPLICATIONS: None (Bootloads on a CPU B development system will now work)

MULTICS CHANGE REQUEST		MCR <u>201</u> Page <u>1</u> of <u>1</u> Pages
TITLE: Qedx addressing	STATUS	DATE
AUTHOR: <u>M. Meer</u>	Written	12/ <u>74</u>
SOURCE: (if external) e.g., "User", "Marketing"	Approved <u>H</u>	<u>12/11/73</u>
	Rejected	
	Postponed	
	Withdrawn	
	Expires	<u>6/11/74</u>

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Fix bug, user request

SUMMARY: Fix addressing bug which gave error on 0a in an empty buffer.
Extend addressing by putting off evaluation of complex numerical addressing as late as possible.

IMPLICATIONS: None

DETAILED PROPOSAL: Examples for a buffer with 5 lines
 1+10 - 7 p prints line 4
 1+10 - 7 /x/ p starts searching for x at line 4
 if . is set to line 2 then
 .6 - 4 p prints line 4
 .6 -4, .6 - 3 p prints lines 4 and 5

All these would currently give address-out-of-buffer errors.

MULTICS CHANGE REQUEST

TITLE: Bugs in listing tape system	STATUS	DATE
	Written	12/4/73
	Approved #	12/11/73
	Rejected	
AUTHOR: M. Meer	Postponed	
	Withdrawn	
	Expires	6/11/74
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	6/11/74

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
Incompatible Change	Marketing Requirement	Implemented in System _____
Extension	Conformance to Standard	Objections/Comments:
Restriction	Increased Consistency	
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Unreported	
	X Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Bug fix

IMPLICATIONS: None

- DETAILED PROPOSAL:
- 1) Incorrect argument processing caused by incorrect usage of the initial attribute in a declare statement. Module is listing_tape_print.pcl.
 - 2) The print_these internal procedure in lts_output.pcl was bumping an index too soon causing incorrect sequencing and out of sync errors when going from one reel to the next while printing.

MULTICS CHANGE REQUEST		MCR <u>203</u> Page <u>1</u> of <u>1</u> Pages
TITLE: <u>Repair defective tape software</u>	STATUS	DATE
	Written	<u>12/5</u>
AUTHOR: <u>N. Morris</u>	Approved	<u># 12/11/73</u>
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	<u>6/11/74</u>

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	<input checked="" type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input checked="" type="checkbox"/> Extension	<input checked="" type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Unreported Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: tape mount label was written in such a way that it did not conform to the standard format for Multics Standard Tapes. This caused certain tapes to be unreadable.

PROPOSAL: Fix tape mount label and upgrade it at the same time to allow use of MTS-500 on Multics.