TO: DISTRIBUTION

FROM: D. R. VINOGRAD

DATE: OCTOBER 22, 1971

SUBJECT: NON OBVIOUS MULTICS SWITCH SETTINGS

The chart shown below is intended to document the non obvious switches on

the H-645 Multics system which can cause system failure or degrade system

performance. The position indicated is that as you face the specified unit

Switch	Location	Setting - Position
Special Interrupt	D170 Controller	Off - Left
Direct Break In	GIOC	Off - Up
Write Verify	D270 Controller	Off - Right
Associative Memory	Processor	On - Down
Operation Unit Overlap	Processor	On - Down
Control Unit Overlap	Processor	On - Down
Timer	Processor	Rt - Up
T and D Switch	Drum Controller Snow Plow	Off - Up